

Home / Recall details

 Close

Motorcycles ; Moto Guzzi, Piaggio

Recall details

Date 2013-10-04**Economy of recall** Germany**Original alert** http://ec.europa.eu/consumers/safety/rapex/alerts/main/index.cfm?event=main.search&case_reference=A12/1360/13
(http://ec.europa.eu/consumers/safety/rapex/alerts/main/index.cfm?event=main.search&case_reference=A12/1360/13)**Economy** -**Manufacturer name** -**Manufacturer website** -

Product details

Type Motor vehicles**Name** Motorcycles ; Moto Guzzi, Piaggio**Description** Motorcycle**Model & Volume** Types: LS, LP, LY, LZ; models: 1200 Sport, Griso, Norge, Stelvio, Bellagio; EC type approvals: e11*2002/24*0614*, e11*2002/24*0211*, e11*2002/24*0692*, e11*2002/24*0152*; production period: 2012-2013**Serious risk** true**Hazard** Injuries The connecting rod on the lower rear shock strut may break without any previously detectable deterioration while driving. The rear wheel then suddenly dips inwards and blocks. The connecting rod on the lower rear shock strut may break without any previously detectable deterioration while driving. The rear wheel then suddenly dips inwards and blocks.**Injury** -

Action	Recall of the product from end users	
Units	-	
Categorisation	show name / code	
segment	Vehicle	
Tags		
	block	
	engine	
	injury	
	motorbike	
	rod	
	vehicle	
	wheel	

DISCLAIMER ▼

© OECD. All rights reserved. [Terms & Conditions \(http://www.oecd.org/termsandconditions/\)](http://www.oecd.org/termsandconditions/) | [Privacy Policy \(http://www.oecd.org/privacy/\)](http://www.oecd.org/privacy/) | [Contact Us \(http://www.oecd.org/contact/\)](http://www.oecd.org/contact/) | [Help/FAQ \(http://www.oecd.org/document/0,3343,en_2649_201185_2509279_1_1_1_1,00.html\)](http://www.oecd.org/document/0,3343,en_2649_201185_2509279_1_1_1_1,00.html) | [MyOECD \(https://www.oecd.org/login\)](https://www.oecd.org/login) | [Site Map \(http://www.oecd.org/sitemap/\)](http://www.oecd.org/sitemap/)