

Home / Recall details

 Close

Motorcycle; Moto Guzzi ; V7, V9 Bobber, V9 Roamer

Recall details

Date	2017-09-26
Economy of recall	Germany
Original alert	https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/index.cfm?event=main.search&case_reference=A12/1343/17 (https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/index.cfm?event=main.search&case_reference=A12/1343/17)
Economy	-
Manufacturer name	-
Manufacturer website	-

Product details

Type	Motor vehicles
Name	Motorcycle; Moto Guzzi ; V7, V9 Bobber, V9 Roamer
Description	Motorcycle
Model & Volume	Type-approval number: e11*168/2013*00251*; type: LD, Type-approval number: e11*168/2013*00254*; type: KV, Type-approval number: e11*168/2013*00210*; type: LH, Type-approval number: e11*168/2013*00211*; type: KP
Serious risk	true

Hazard	Injuries Rubbing of the front brake line against the secondary air system may lead to leakage of the brake fluid for the front brake. Failure of the front wheel brake could lead to an accident. Rubbing of the front brake line against the secondary air system may lead to leakage of the brake fluid for the front brake. Failure of the front wheel brake could lead to an accident.		
Injury	-		
Action	Recall of the product from end users		
Units	-		
Categorisation	show name / code		
segment	Vehicle		
Tags	brake brake fluid engine injury motorbike vehicle wheel		

DISCLAIMER ▼

© OECD. All rights reserved.Terms & Conditions (<http://www.oecd.org/termsandconditions/>) |
Privacy Policy (<http://www.oecd.org/privacy/>) | Contact Us (<http://www.oecd.org/contact/>) |
Help/FAQ (http://www.oecd.org/document/0,3343,en_2649_201185_2509279_1_1_1_1,00.html) |
MyOECD (<https://www.oecd.org/login>) | Site Map (<http://www.oecd.org/sitemap/>)