



Home / Recalls / REC-001077

PETER STEVENS IMPORTERS PTY. LTD. - MOTO GUZZI V9

Recall number

REC-001077

PRA number

2018/16535

Campaign number

PSR05

Original published date

22 January 2018

Make

MOTO GUZZI

Model

V9

Affected units

80

Images

1 sur 4 18/04/2025 18:15



Identifying features

see attached VIN list

VIN (Vehicle identification number)



REC-001077-VIN-List-1.csv (CSV, 1.51 KB)

What are the defects?

Part of the ABS system pipe-work may contact or rub against other parts of the engine.

What are the hazards?

This may lead to damage of the brake pipes and in the worst case scenario, lead to the loss of braking capability.

What should consumers do?

Consumers should contact their nearest authorised Moto Guzzi dealer and arrange a time for an inspection and the installation of a specific pipe support bracket. A full list of authorised dealers can be found on the "Find a Dealer" page - http://motoguzzi.com.au/dealers.html

For further information consumers can go to Moto Guzzi Australia at http://www.motoguzzi.com.au and click on the 'Contact Us' link.

Supplier details

PETER STEVENS IMPORTERS PTY. LTD.

2 sur 4 18/04/2025 18:15

Responsible regulator

Department of Infrastructure, Transport, Regional Development, Communications and the Arts is the responsible regulator for this recall.



Product type

Motor Bikes MOTO GUZZI

Share this page 😝 🎳 🔀







I want to...



Receive email updates



Subscribe to RSS



Browse all recalls

18/04/2025 18:15